

<b>Causes:</b>	<ul style="list-style-type: none"> <li>• Fuel injector 10</li> <li>• Running out of fuel</li> <li>• EVAP canister purge valve</li> <li>• Fuel pressure</li> <li>• Evaporative emission system</li> <li>• Exhaust gas recirculation (EGR) system</li> <li>• Base engine</li> <li>• Misfire monitor neutral profile correction has not been relearned since the last mechanical repair</li> </ul>		
<b>Diagnostic Aids:</b>	<p>Misfire is defined as lack of combustion in a cylinder due to absence of spark, incorrect fuel metering, low compression, or any other cause.</p> <p>The malfunction indicator lamp (MIL) blinks once per second when a misfire severe enough to cause catalyst damage is detected. If the MIL is on steady state due to a misfire, this indicates the threshold for emissions was exceeded and caused the vehicle to fail an inspection and maintenance tailpipe test.</p>		
<b>Application</b>	<b>Key On Engine Off</b>	<b>Key On Engine Running</b>	<b>Continuous Memory</b>
All	GO to Pinpoint Test <a href="#">HD</a> .		

### P0313 - Misfire Detected With Low Fuel

<b>Description:</b>	This DTC sets when an engine misfire fault is detected with low fuel level.		
<b>Possible Causes:</b>	<ul style="list-style-type: none"> <li>• Customer driving habits</li> <li>• Low fuel or no fuel in tank (less than 1/8 tank)</li> </ul>		
<b>Diagnostic Aids:</b>	Verify the fuel level is above 1/8 before diagnosing engine misfire DTCs.		
<b>Application</b>	<b>Key On Engine Off</b>	<b>Key On Engine Running</b>	<b>Continuous Memory</b>
All	GO to Pinpoint Test <a href="#">HD</a> .		

### P0315 - Crankshaft Position System Variation Not Learned

<b>Description:</b>	The PCM has not learned the crankshaft pulse wheel tooth spacing. This DTC disables the misfire monitor.		
<b>Possible Causes:</b>	<ul style="list-style-type: none"> <li>• PCM reprogramming</li> <li>• PCM replacement</li> <li>• Internal PCM non-volatile random access memory (NVRAM) error</li> </ul>		
<b>Diagnostic Aids:</b>	Complete the Misfire Monitor Neutral Profile Correction procedure using the scan tool.		
<b>Application</b>	<b>Key On Engine Off</b>	<b>Key On Engine Running</b>	<b>Continuous Memory</b>
All	Refer to the Description, Possible Causes and Diagnostic Aids for the DTC.		

### P0316 - Misfire Detected On Startup (First 1000 Revolutions)

<b>Description:</b>	This DTC sets in addition to any type B misfire DTC which occurs in the first 1,000 revolution test interval following engine start.		
<b>Possible Causes:</b>	<ul style="list-style-type: none"> <li>• Damaged crankshaft position (CKP) sensor</li> <li>• Damaged ignition system</li> <li>• Damaged fuel injectors</li> <li>• Running out of fuel</li> <li>• Fuel quality</li> <li>• Base engine</li> <li>• Damaged PCM</li> </ul>		

<b>Diagnostic Aids:</b>	Freeze frame data and the DTC P03xx are also stored, indicating which cylinder the misfire occurred.		
<b>Application</b>	<b>Key On Engine Off</b>	<b>Key On Engine Running</b>	<b>Continuous Memory</b>
All	GO to Pinpoint Test <u>HD</u> .		

### P0320 - Ignition/Distributor Engine Speed Input Circuit

<b>Description:</b>	This DTC sets when several erratic profile ignition pickup (PIP) pulses have occurred in the crankshaft position (CKP) sensor signal within a calibrated time period when the camshaft speed exceeds the equivalent speed of engine idle.		
<b>Possible Causes:</b>	<ul style="list-style-type: none"> <li>• CKP+ circuit intermittent open (VR type)</li> <li>• CKP- circuit intermittent open (VR type)</li> <li>• CKP circuit intermittent open (Hall effect)</li> <li>• VREF circuit intermittent open (Hall effect)</li> <li>• SIGRTN circuit intermittent open (Hall effect)</li> <li>• CKP+ circuit intermittent short to voltage (VR type)</li> <li>• CKP- circuit intermittent short to voltage (VR type)</li> <li>• CKP circuit intermittent short to voltage (Hall effect)</li> <li>• VREF circuit intermittent short to voltage (Hall effect)</li> <li>• SIGRTN circuit intermittent short to voltage (Hall effect)</li> <li>• CKP+ circuit intermittent short to ground (VR type)</li> <li>• CKP- circuit intermittent short to ground (VR type)</li> <li>• CKP circuit intermittent short to ground (Hall effect)</li> <li>• VREF circuit intermittent short to ground (Hall effect)</li> <li>• SIGRTN circuit intermittent short to ground (Hall effect)</li> <li>• CKP sensor incorrectly installed</li> <li>• Damaged CKP sensor</li> <li>• Incorrect, damaged or corroded connections</li> <li>• Arcing secondary ignition components (coil, wires and plugs)</li> <li>• Arcing relays or other high current devices (cooling fan or starter motor)</li> <li>• On board 2 way radio transceiver</li> <li>• Radio frequency interference or electromagnetic interference from an external source</li> <li>• Incorrectly grounded high power aftermarket equipment</li> </ul>		
<b>Diagnostic Aids:</b>			
<b>Application</b>	<b>Key On Engine Off</b>	<b>Key On Engine Running</b>	<b>Continuous Memory</b>
All	GO to Pinpoint Test <u>A</u> .		

### P0322 - Ignition/Distributor Engine Speed Input Circuit No Signal

<b>Description:</b>	This DTC sets when the crankshaft position (CKP) sensor profile ignition pickup (PIP) pulse is missing for greater than a calibrated number of camshaft revolutions when the camshaft speed exceeds the equivalent speed of engine idle.		
<b>Possible Causes:</b>	<ul style="list-style-type: none"> <li>• CKP+ circuit intermittent open (VR type)</li> <li>• CKP- circuit open (VR type)</li> <li>• CKP circuit open (Hall effect)</li> <li>• VREF circuit open (Hall effect)</li> <li>• SIGRTN circuit open (Hall effect)</li> <li>• CKP+ circuit short to voltage (VR type)</li> <li>• CKP- circuit short to voltage (VR type)</li> <li>• CKP circuit short to voltage (Hall effect)</li> <li>• VREF circuit short to voltage (Hall effect)</li> <li>• SIGRTN circuit short to voltage (Hall effect)</li> <li>• CKP+ circuit short to ground (VR type)</li> </ul>		