



E187067



14. Tighten the differential bearing cap bolts.
Torque: 71 lb.ft (96 Nm)