



2025-12-05 18:57:39

2021 Ford Mustang GT Coupe, 5.0 L, V8

Readiness Monitors

Confirmed Emissions Fault Codes: 0
MIL is On: No

Misfire	Complete
Fuel System	Incomplete
Components	Complete
Catalyst	Incomplete
Heated Catalyst	Not Supported
Evaporative System	Incomplete
Secondary Air System	Not Supported
Gasoline Particulate Filter	Not Supported
Oxygen Sensor	Incomplete
Oxygen Sensor Heater	Incomplete
EGR and/or VVT System	Incomplete

Warmups Since Code Clear: 0
Distance Since Code Clear: 0 Km / 0 Miles

2 Fault Codes Detected

0x7E8 Engine Control Module	
P0124	Pending
Throttle/Pedal Position Sensor A Intermittent	
U2110	Pending
Throttle/Pedal Position Sensor/Switch A Communication Circuit High	

▶ Codes Queried from 1 Controller