

Find, Easy to Deal With"



PIKE (I-275 & BEECHMONT)

INNATI, OHIO 45245

www.beechmontford.com

TRUAX

MILEAGE IN/ OUT	TAG
5408 / 5418	TR388
PAYMENT	INV. DATE
CASH	21MAR17

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A CUSTOMER STATES THAT THE COOLANT IS BOTTLE IS EMPTY AND THE OIL HAS
DOUBLED PLEASE CHECK AND ADVISE

CAUSE:

6007E ENGINE EXCHANGE - DIAGNOSIS

(6009/6006/6007/6012) - M

8553 WP4

(N/C)

1 FR3Z*6006*B SERVICE ENGINE ASY

(N/C)

16 *W714870*S430 NUT

(N/C)

2 FR3Z*9448*A GASKET

(N/C)

1 FR3Z*9424*M MANIFOLD ASY - INLET

(N/C)

4 VC*3DIL*B ANTI-FREEZE

(N/C)

1 BR3Z*6A664*A HOSE - VENT

(N/C)

6007A ENGINE ASSEMBLY - REMOVE AND INSTALL (6007)

- L

8553 WP4

(N/C)

6007A34 SERVICE ENGINE ASSEMBLY - FR (FORD

REMANUFACTURED ENGINE)/OEM LONG BLOCK -

REPLACE (6007/6006) - L

8553 WP4

(N/C)

6007E1 INSPECT AND DETERMINE ENGINE CONDITION -

CHECK (6009/6006/6007/6012/6675) - L

8553 WP4

(N/C)

6007AXQ ENGINE ASSEMBLY - REMOVE AND INSTALL

(6007) - L EXTRA TIME FOR A POST-REPAIR ROAD

TEST.

8553 WP4

(N/C)

FC: L85 D8 PART#: COUNT:

CLAIM TYPE:

AUTH CODE:

8553

PARTS:	0.00	LABOR:	0.00	OTHER:	0.00	TOTAL LINE A:	0.00
--------	------	--------	------	--------	------	---------------	------

5418

OPERATION 6007E, 6007A, 6007A34, 6007E1, 6007AXQ

HOTLINE CONTACT ID 111762559

We thank you for your business and appreciate your support! If you need assistance, or have any questions, please feel free to contact me directly.

Thank You,
Jeff Fithen, General Manager
513-752-6611 ext 1102
jefffithen@bmtford.com

Like us on Facebook
Visit us online at www.Beechmont Ford.com for all of your automotive needs.

Disclaimer of Warranties
Any warranties on the products sold herein are those made by the manufacturer of those products. Seller hereby expressly disclaims all warranties either express or implied, including any implied warranties of merchantability or fitness for a particular purpose (regarding any products or services provided, unless otherwise indicated on the service repair order). This dealership neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of said products or services. This disclaimer by the dealership in no way affects the terms or performances of the manufacturer's warranty.

CUSTOMER SIGNATURE

DESCRIPTION	TOTALS
LABOR AMOUNT	
PARTS AMOUNT	
GAS, OIL, LUBE	
SUBLET AMOUNT	
MISC. CHARGES	
TOTAL CHARGES	
LESS INSURANCE	
SALES TAX	
PLEASE PAY THIS AMOUNT	

Customer Copy