

Control # 012220191022

Date Taken 10/21/2019

Service Meter Reading 9350

Fluid Run Time 5500

Fluid Added Gal / Qts 0 / 0

Fluid Status Changed

Filter Changed Yes

Anti-Freeze Negative

Fuel Negative

Water Negative

Visc 100C 10.9

Iron (FE) 18

Chromium (CR) 1

Lead (PB) 0

Copper (CU) 4

Tin (SN) 1

Aluminum (AL) 0

Nickel (NI) 0

Silver (AG) 1

Silicon (SI) 9

Potassium (K) 2

Sodium (NA) 1

Boron (B) 50

Magnesium (MG) 646

Calcium (CA) 1029

Barium (BA) 0

Phosphorus (P) 662

Zinc (ZN) 714

Molybdenum (MO) 76

Titanium (TI) 0

Vanadium (V) 3

Fuel % 1

**Lab One Inc.**

Oil Analysis since 1985

Mail to: PO Box 20210 - Phoenix, AZ 85036-0210

Ship to: 101 W Mohave St. - Phoenix AZ 85003

Phone

Local: 480-839-5221

Toll Free: 866-652-2663

Fax: 480-839-9987

Normal

1 of 1

10/22/2019

Make / Model

FORD MUSTANG 5.0 GT

Unit/Serial

FORD MUSTANG/

Compartment

Gasoline Engine

Fluid Type

MOBIL 1 5W30

WO / Reference**Current Interpretation**

No abnormal wear detected. Viscosity is in the Sae 30 range (9.30cst To 12.49cst). Fuel content within acceptable limits.

0000008401

Chris Barnes
437 E Mountain Sage Dr
Phoenix, Az 85048

Registered By

STEPHAN TURPEN

Interpreted By

JASON KRONLUND