

Customer Satisfaction Program 19B34
 Certain 2018-2019 Model Year Mustang GT350 Vehicles
 Gearshift Lever Assembly Reverse Lock-Out

LABOR ALLOWANCES

Description	Labor Operation	Labor Time
Replace the gearshift lever assembly	19B34B	1.0 Hours

PARTS REQUIREMENTS / ORDERING INFORMATION

Part Number	Description	Order Quantity	Claim Quantity
FR3Z-7210-G	Gearshift lever assembly	1	1
4R3Z-7C211-AA	Gearshift lever threaded pin	1	1
W520101-S440	Nut – gearshift lever to body studs (2 req., 4 per package)	1	2
N800594-S101	Bolts – driveshaft to transmission flange (4 req., 4 per package)	1	4
FR3Z-7213-C	Shift knob – gear change lever	1	1

Order your parts requirements through normal order processing channels. To guarantee the shortest delivery time, an emergency order for parts must be placed.

DEALER PRICE

For latest prices, refer to DOES II.

PARTS RETENTION AND RETURN

Follow the provisions of the Warranty and Policy Manual, Section 1 - WARRANTY PARTS RETENTION AND RETURN POLICIES.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.