

TRANSMISSION
6 Speed Transmission

POWER
Power Steering
Power Brakes
Power Windows
Power Locks
Power Mirrors
Power Driver Seat
Power Passenger Seat

DECOR
Dual Mirrors
Tinted Glass
Console/Storage

CONVENIENCE
Stereo

Air Conditioning
Intermittent Wipers
Tilt Wheel
Cruise Control
Rear Defogger
Keyless Entry
Alarm
Message Center
Steering Wheel Touch Controls
Telescopic Wheel
Backup Camera w/Parking Sensors

Search/Seek
CD Player
Auxiliary Audio Connection
SAFETY
Drivers Side Air Bag
Passenger Air Bag
Anti-Lock Brakes (4)
4 Wheel Disc Brakes
Front Side Impact Air Bags
Head/Curtain Air Bags
Postraction
Hands Free Device

SEATS
Cloth Seats
Bucket Seats

OTHER
Clear Coat Paint
Fog Lamps
Traction Control
Stability Control
Rear Spoiler
Xenon Headlamps
Power Trunk/Gate Release

PAINT
Aluminum/Alloy Wheels
Reclining/Lounge Seats

WHEELS

Year: 2015
Make: FORD
Model: MUSTANG GT

Color: YELLOW Int:
Body Style: 2D CPE
Engine: 8-5.0L-FI

License: [Redacted]
State: MD
VIN: [Redacted]
Production Date:
Odometer:
Condition:

9161

VEHICLE

Insured:
Type of Loss:
Point of Impact: 06 Rear
Liability

Owner Policy #: [Redacted]
Date of Loss: 07/03/2015 11:50 AM
Deductible:

Appraiser Information: [Redacted]

Inspection Location:
SDR SMALL DAMAGE REPAIR
100 Cockeysville Rd
Cockeysville, MD 21030
Drive-In
(410) 771-0900 Day

Repair Facility:
LEADING EDGE
MT. WASHINGTON, MD

Written By: [Redacted]

Estimate of Record

GEICO Claims
Visit us at GEICO.com
Auto Damage Claims
5260 Western Ave.
Chevy Chase, MD 20815
Phone: (410) 598-5244
Fax: (877) 303-2015

Claim #: [Redacted]
Workfile ID: [Redacted]