











Before Measurements



Current Measurements



... values are not within specification. Tire wear, handling and safety problems may result.