

Claim #:   
 Workfile ID:

Estimate of Record

2015 FORD MUSTANG GT 2D CPE 8-5.0L-FI YELLOW

Line	Oper	Description	Qty	Extended Price \$	Labor	Paint
------	------	-------------	-----	-------------------	-------	-------

1	R&I	REAR BUMPER				
2	R&I	R&I bumper cover	1.2			
3	Rpr	Bumper cover w/park sensors	3.5			2.0
4	*	Add for Clear Coat				1.4
5	R&I	Valance panel	0.3			
6	R&I	Park sensor	0.1			
7	R&I	Park sensor	0.1			
8	R&I	Park sensor	0.1			
9	R&I	Park sensor	0.1			
10	R&I	REAR LAMPS				
11	R&I	RT Tail lamp assy w/o chrome stripe	0.4			
12	R&I	LT Tail lamp assy w/o chrome stripe	0.4			
13	R&I	Backup lamp	1	900.00		
14	R&I	RT Side marker lamp	0.1			
15	R&I	LT Side marker lamp	0.1			
16	R&I	RT License lamp	0.1			
17	R&I	LT License lamp	0.1			
18	R&I	TRUNK LID				
19	*	Align Trunk lid w/spoiler	0.5			
20	*	Rpr Trunk lid w/spoiler	0.2			0.0
21	#	CHECK AND ADVISE REAR BODY PANEL	1			
22	#	CHECK AND ADVISE TRUNK GAPS AT QTRS	1			
23	#	Subl Flex additive	1	3.00		
24	#	OTHER CHARGES				
25	#	E.P.C.	1	3.00		
<b>SUBTOTALS</b>				<b>906.00</b>	<b>7.4</b>	<b>3.4</b>

NOTES

Line 3: RPR TIME INCLUDES HEATING TO RESHAPE. BLEND WITHIN PANEL, FULL CLEAR COAT  
 Line 20: BUFF SCRS ON UNDERSIDE. CUST IS ADAMANT SCUFFS ARE CLAIM-RELATED.  
 Prior Damage Notes: NONE VISIBLE.