




Grapevine Ford
801 E Hwy 114
Grapevine, TX 76051
(877) 418-2969
<http://www.grapevineford.com>

Vehicle Scan Summary - 2/24/2016, 9:21 AM

Recommendation



Service Needs







Diagnostic Notes

- Front Tires Have Equal Tread Wear.
- Rear Tires Have Equal Tread Wear.
- Rear tires have less tread than the front. Use Caution in Wet/Snowy Conditions.
- Do not rotate tires.
- Tire widths all match.



Braking Distance

(70 MPH - Wet Surface)



GOOD

MARGINAL

REPLACE